


FIG. 1






FIG. 2a






FIG. 2b








FIG. 3c



PICK HEAD SUCKING SOLDER BALLS UP




FIG. 3d




FIG. 4




FIG. 5a




FIG. 5b




FIG. 5c




FIG. 5d




FIG. 5e




FIG. 5f

